

**Ref: FAQ0156****Version: 1.0****Title –SoundSens screeching noise****Made By: AB 16/09/15****(Issue 2)**

SoundSens high pitched screeching noise in sound recording

The high pitched sound that can occur in the pod recording is normal and only happens when there is very low or no detectable leak noise. It is caused by the pod 'winding' its gain up to the maximum. It occurs more often on concrete or plastic pipes. It does not happen when there is leak noise present.

Document History:

| Edition | Date of Issue | Modification | Notes |
|----------------|----------------------|---------------------|--------------|
| 1st | 19/04/12 | Release | |
| 2nd | 16/09/15 | Format and update | |
| | | | |