|		Ref: FAQ0169	Version: 1.0
HWM	Palmer environmental / RADIO-TECH / RADCON TECHNOLOGIES / Fcs Fluid Conservation Systems	Title – MAST Software install error	
		Made By: AB 17/09/15	(Issue 2)

MSCOMM32.OCX error message when loading MAST software

After installation of the MAST software, you may encounter the below failure (after you have clicked the OK button on the 'Initial COMM port setting' popup).

To overcome this error, you must install the MSCOMM32.ocx file. This can easily be downloaded from the web by typing in 'MSCOMM32.ocx download' into a search agent (e.g. Google).

When you are downloading the file, save it to the same location where your MAST software has downloaded and installed .

When you run the MAST software, it should now run correctly without the error.

Document History:

Edition	Date of Issue	Modification	Notes
1st		Release	
2nd	17/09/15	Format update	