



Ref: FAQ0152

Version: 1.0


Title – SoundSens velocity crossed out

Made By: AB 16/09/15

(Issue 2)

## SoundSens graphs – what the crossing out of distance values indicate

The 'crossed' lines through the distance reading on the graph is not a problem. It is the software identifying a warning to you. It indicates that there are 'multiple paths' in the pipe layout so the leak position is not definite. Basically before you start digging holes to find the leak you should try and localize it further with another test covering a smaller area of the pipe network.



### Document History:

Edition	Date of Issue	Modification	Notes
1st	19/04/12	Release	
2nd	16/09/15	New format and update	